

Try to define the contour and outline curves of the given surfaces.

Sketch the outline with blue coloured pencil and contour curves with green coloured pencil .

